

GENERATOR COPY

SALVAGE YARD

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Northridge Torrance, CA 90502				A.State Manifest Document Number 84924336			
4. Generator's Phone (213 533-6677)				B.State Generator's ID			
5. Transporter 1 Company Name J. C. Liquid Waste Disposal		6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7		C.State Transporter's ID 64152			
7. Transporter 2 Company Name		8. US EPA ID Number		D.Transporter's Phone 213 268-3137			
9. Designated Facility Name and Site Address CASMALIA P.O. Box E NTU Road Casmalia, CA 93429		10. US EPA ID Number C A D 0 2 0 7 4 8 1 2 5		E.State Transporter's ID			
				F.Transporter's Phone			
				G.State Facility's ID C A D 0 2 0 7 4 8 1 2 5			
				H.Facility's Phone 805 937-8449			
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Waste flammable - Solid NOS UN1325				073	DM	00018	Y 461
b. Waste Sodium Hydroxide - Solid Corrosive UN1823 RQ10001454 RQ10001454				006	DM	00002	Y 123
c.							
d.							
J. Additional Descriptions for Materials Listed Above A. Paint sludge & vermiculite 3 absorbent B. Sodium Hydroxide & solid & vermiculite 3 absorbent				K.Handling Codes for Wastes Listed Above 03			
15. Special Handling Instructions and Additional Information Guide # 32 Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.							
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.							
Printed/Typed Name Donald C. Gerber				Signature <i>Donald C. Gerber</i>		Date 04/11/86	
17. Transporter 1 Acknowledgement of Receipt of Materials				Signature <i>William Spence</i>		Date 04/11/86	
Printed/Typed Name William Spence				Signature		Date	
18. Transporter 2 Acknowledgement of Receipt of Materials				Signature		Date	
Printed/Typed Name				Signature		Date	
19. Discrepancy Indication Space RECEIVED							
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. # 72457-18, 02016							
Printed/Typed Name Casmalia Resources				Signature <i>Donald C. Gerber</i>		Date 14/1/86	

SALVAGE YARD

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Northridge Torrance, CA 90502			A. State Manifest Document Number 84924336		B. State Generator's ID	
4. Generator's Phone (213 533-6677)			C. State Transporter's ID 64152		D. Transporter's Phone 213 268-3137	
5. Transporter 1 Company Name J. C. Liquid Waste Disposal			6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7		E. State Transporter's ID	
7. Transporter 2 Company Name			8. US EPA ID Number		F. Transporter's Phone	
9. Designated Facility Name and Site Address CASMALIA P.O. Box E NTU Road Casmalia, CA 93429			10. US EPA ID Number C A D 0 2 0 7 4 8 1 2 5		G. State Facility's ID 805 937-8449	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol
a. Waste flammable - Solid NOS UN1325			073	DM	00018	Y
b. Waste Sodium Hydroxide - Solid Corrosive UN1823 RQ10001454			006	DM	00002	Y
c.						
d.						
J. Additional Descriptions for Materials Listed Above A. Paint sludge & vermiculite 3 absorbent B. Sodium Hydroxide & solid & vermiculite 3 absorbent			K. Handling Codes for Wastes Listed Above			
15. Special Handling Instructions and Additional Information Guide # 32 Use gloves, goggles, respirator - Do not go near open flame or inhale fumes.						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national governmental regulations.						
Printed/Typed Name Donald C. Gerber			Signature sb [Signature]		Date Month Day Year 04/17/86	
17. Transporter 1 Acknowledgement of Receipt of Materials			Signature [Signature]		Date Month Day Year 04/17/86	
Printed/Typed Name William Spence			Signature [Signature]		Date Month Day Year 04/17/86	
18. Transporter 2 Acknowledgement of Receipt of Materials			Signature		Date Month Day Year	
Printed/Typed Name			Signature		Date Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.						
Printed/Typed Name			Signature		Date Month Day Year	